



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining
JOHN R. BAZA
Division Director

Inspection Report

Reviewed PPB

Minerals Regulatory Program

Date Submitted: 07/31/2013

Mine Name: Smokey Joe	Permit Number: M/049/0002	Permit Fees: Paid		
Operator Name: Interstate Brick Co.	Inspection Date: June 20, 2013	Bond Amount: \$62,400.00		
Inspector(s): A. Abate, L. Kunzler, T. Nicolaysen	Time: 11:00 AM	Bond Escalation: past due 9/2011		
Others:	Mine Status: Inactive			
Elements of Inspection		Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages/Erosion Control		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Soils		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection

In response to a Division Order issued on June 5, 2013, requiring the site to be reclaimed, the operator contacted the Division to inform us that reclamation was performed at the site. Inspected the site to see what was done.

Inspection Summary

ATV tracks observed on the highwall on a prior inspection were gone. Large boulders were placed on site to block access to the mine. The dumps on the west side of the mine were still too high and need to be graded down. A fair amount of trash is still present.

Conclusions and Recommendations

Verify that dumps on the far west side are part of the permit area. These slopes should be graded if they are. Request operator to meet with Division in the field to discuss reclamation work.

Inspector's Signature: [Signature]

CC: John Hewitt, Interstate Brick Co. - 9780 S 5200 W, West Jordan, UT 84088

File: /NRLOGMFS1/ogm/GROUPS/MINERALS/WP/M049-Utah/M0490002-SmokeyJoe/Inspections/Insp-06202013.pdf



Highwall on the west side of the mine facing northwest is still too high - needs grading.



View of the boulders that have been placed separating the mine from the road. The boulders for the most part block access but there are still areas where access is possible for off road vehicles.



Highwall view: ATV tracks have been removed since May 2013 inspection.



Trash and shell casing are still present at the site and need to be disposed of.